



Part Number: 1375M39G15

Part Description: Forward Fan Case  
Outer Liner Segments

## Specifications

|                              |               |
|------------------------------|---------------|
| Product Families:            | Nacelles      |
| Product Group:               | Fan Cowl      |
| Part Number                  | 1375M39G15    |
| Root Part Number             | 1375M39GXX    |
| ATA Chapter 2 Digit          | 72            |
| ATA Chapter 4 Digit          | 72-22         |
| ATA Chapter 6 Digit          | 72-22-02      |
| MFR / Manufacture -CAGE Code | Boeing        |
| Application                  | CF6 - 50 & 80 |

## Repair

|                      |                                       |
|----------------------|---------------------------------------|
| Part Number          | 1375M39G15                            |
| Description          | Forward Fan Case Outer Liner Segments |
| Repair Manual- CMM   | CMM                                   |
| Bench Check & Advise | Yes                                   |
| Repair               | Yes                                   |
| Repair Facility      | Hialeah                               |

## Logistics

|             |                                       |
|-------------|---------------------------------------|
| Part Number | 1375M39G15                            |
| Description | Forward Fan Case Outer Liner Segments |

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

**630 Aerospace where quality is built in not inspected.**



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737