



Part Number: TY1541-51

Part Description: Upper Feedback Actuator

## Specifications

<b>Product Families:</b>	Accessories
<b>Product Group:</b>	Engine Systems Accesories
<b>Part Number</b>	TY1541-51
<b>Root Part Number</b>	TY1541-51
<b>ATA Chapter 2 Digit</b>	78
<b>ATA Chapter 4 Digit</b>	78-32
<b>ATA Chapter 6 Digit</b>	78-32-48
<b>MFR / Manufacture -CAGE Code</b>	Goodrich
<b>Application</b>	V2500

## Repair

Part Number	TY1541-51
Description	Upper Feedback Actuator
Repair Manual- CMM	CMM
Bench Check & Advise	Yes
Repair	Yes
Overhaul	Yes
Repair Facility	Hialeah

## Logistics

Part Number	TY1541-51
Description	Upper Feedback Actuator

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

**630 Aerospace where quality is built in not inspected.**



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737