



Part Number: 114T0201-45

Part Description: Thermal Anti-icing duct seal door assembly

Specifications

| | |
|------------------------------|-------------|
| Product Families: | Structures |
| Product Group: | Doors |
| Part Number | 114T0201-45 |
| Root Part Number | 114T0201-45 |
| ATA Chapter 2 Digit | 57 |
| ATA Chapter 4 Digit | 57-41 |
| ATA Chapter 6 Digit | 57-41-10 |
| MFR / Manufacture -CAGE Code | Boeing |
| Application | B757 |

Repair

| | |
|----------------------|--|
| Part Number | 114T0201-45 |
| Description | Thermal Anti-icing duct seal door assembly |
| Repair Manual- CMM | CMM |
| Bench Check & Advise | Yes |
| Repair | Yes |
| Overhaul | Yes |
| Repair Facility | Miami Lakes |

Logistics

| | |
|-------------|--|
| Part Number | 114T0201-45 |
| Description | Thermal Anti-icing duct seal door assembly |

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

630 Aerospace where quality is built in not inspected.



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737