



Part Number: 1375M39G09

Part Description: Forward Fan Case
Outer Liner Segments

Specifications

Product Families:	Nacelles
Product Group:	Fan Cowl
Part Number	1375M39G09
Root Part Number	1375M39GXX
ATA Chapter 2 Digit	72
ATA Chapter 4 Digit	72-22
ATA Chapter 6 Digit	72-22-02
MFR / Manufacture -CAGE Code	Boeing
Application	CF6 - 50 & 80

Repair

Part Number	1375M39G09
Description	Forward Fan Case Outer Liner Segments
Repair Manual- CMM	CMM
Bench Check & Advise	Yes
Repair	Yes
Repair Facility	Hialeah

Logistics

Part Number	1375M39G09
Description	Forward Fan Case Outer Liner Segments

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

630 Aerospace where quality is built in not inspected.



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737