



Part Number: 1798M92G05

Part Description: Accelerometer Compressor cables

Specifications

Product Families:	Harnesses
Product Group:	Engine Systems
Part Number	1798M92G05
Root Part Number	1798M92G05
ATA Chapter 2 Digit	77
ATA Chapter 4 Digit	77-21
ATA Chapter 6 Digit	77-21-62
MFR / Manufacture -CAGE Code	BAE Systems
Application	CF6 - 50 & 80

Repair

Part Number	1798M92G05
Description	Accelerometer Compressor cables
Repair Manual- CMM	CMM
Bench Check & Advise	Yes
Repair	Yes
Repair Facility	Hialeah

Logistics

Part Number	1798M92G05
Description	Accelerometer Compressor cables

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

630 Aerospace where quality is built in not inspected.



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737