



Part Number: 314T4320-19

Part Description: Turbine Exhaust Plug Assembly

## Specifications

Product Families:	Aircraft Interiors
Product Group:	Side Panels & Windows
Part Number	314T4320-19
Root Part Number	314T4320-XX
ATA Chapter 2 Digit	78
ATA Chapter 4 Digit	78-11
ATA Chapter 6 Digit	78-11-15
MFR / Manufacture -CAGE Code	Boeing
Application	CF6 - 50 & 80

## Repair

Part Number	314T4320-19
Description	Turbine Exhaust Plug Assembly
Repair Manual- CMM	CMM
Bench Check & Advise	Yes
Repair	Yes
Overhaul	Yes
Repair Facility	Miami Lakes

## Logistics

Part Number	314T4320-19
Description	Turbine Exhaust Plug Assembly

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

**630 Aerospace where quality is built in not inspected.**



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737