



Part Number: 642-3802-519

Part Description: Thrust Reverser Door Assembly

## Specifications

|                              |                  |
|------------------------------|------------------|
| Product Families:            | Nacelles         |
| Product Group:               | Thrust Reversers |
| Part Number                  | 642-3802-519     |
| Root Part Number             | 642-3802-XXX     |
| ATA Chapter 2 Digit          | 78               |
| ATA Chapter 4 Digit          | 78-32            |
| ATA Chapter 6 Digit          | 78-32-35         |
| MFR / Manufacture -CAGE Code | Rohr             |
| Application                  | A320             |

## Repair

|                      |                               |
|----------------------|-------------------------------|
| Part Number          | 642-3802-519                  |
| Description          | Thrust Reverser Door Assembly |
| Repair Manual- CMM   | CMM                           |
| Bench Check & Advise | Yes                           |
| Repair               | Yes                           |
| Repair Facility      | Miami Lakes                   |

## Logistics

|             |                               |
|-------------|-------------------------------|
| Part Number | 642-3802-519                  |
| Description | Thrust Reverser Door Assembly |

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

**630 Aerospace where quality is built in not inspected.**



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737